



№ Zest. iL pęchego el. wysłowycho		Poz. 17		Suma 6 X		Wynik	
№	Typ	Poz.	Materiał	Strukt	Profil	Materiał	Diagnost
1	3	17	KS	1	0,062/0,0593	5355	961
2	3	1011	KS	1	BL.21460	5355	180
3	3	1039	KS	1	0,062/0,0593	5355	985
4	3	1062	KS	1	BL.20111	5355	236
5	3	1056	KS	1	BL.870	5355	205
6	3	1063	KS	1	BL.6740	5355	50



№ Zest.		Nazwa		Sztuka		Materiał		Długość		Kolor		Dłm.	
Nr.	Imię	Imię	Nazwa	Sztuka	Procent	Materiał	Długość	Kolor	Dłm.				
1	18	KS	18	1	0,00	18	18	18	18				
2	3	1039	KS	1	0,00	1039	1039	1039	1039				
3	3	1046	KS	1	0,00	1046	1046	1046	1046				
4	3	1047	KS	1	0,00	1047	1047	1047	1047				
5	3	1053	KS	1	0,00	1053	1053	1053	1053				
6	3	1061	KS	1	0,00	1061	1061	1061	1061				
7	3	1064	KS	1	0,00	1064	1064	1064	1064				
8	3	1066	KS	1	0,00	1066	1066	1066	1066				
9	3	1069	KS	1	0,00	1069	1069	1069	1069				

[illegible][illegible]

STAL: S355

POZIOMY BUDYNEK	
+16,25 ± 62,36 m.p.m.	+5
+12,97 ± 79,67 m.p.m.	+4
+9,69 ± 76,39 m.p.m.	+3
+6,41 ± 73,11 m.p.m.	+2
+3,13 ± 69,83 m.p.m.	+1
± 0,00 ± 66,70 m.p.m.	± 0
-2,65 ± 64,05 m.p.m.	-1

[illegible]